


USE THIS TROUBLE SHOOTING FLOW CHART TO DIAGNOSE
A RADIO CONTROLLED CHOKER BELL WHICH FAILS TO SET.



Johnson industries / elevanja ltd

Vancouver BC Canada -- Tel: 604 940 4555 Fax: 604 940 4565
 Toronto ON Canada -- Tel: 416 213 9991 Fax: 416 213 9992
 Bridgewater SOM England -- Tel: 01278 456411 Fax: 01278 429949

RCC MECHANICAL TROUBLE SHOOTING - SET

BY: ST DATE: 921125
 SC: REV.: 000120
 PATH: rcc/mch/manual

DWG. NO.
A2010-M03-3